MINTARO®





Mintaro

min•tar•0 | min-tahr-oh | derivative of Spanish origin meaning)
"camping place" or "resting place."



Due to continuous product improvement, please see the website for the latest in standards and options, specifications, and technical data. Go to www.holidayrambler.com.

Weights*	26RKS	26BHS	27BH	27RBS	28RLS	30QBHS	31BHDS	32RLS
GVWR	7,526	7,600	7,539	10,896	7,625	10,893	10,976	TBD
Axle(s) Weight	4,000	4,612	3,992	4,712	4,964	5,674	5,874	TBD
Unloaded Vehicle Weight	4,526	5,212	4,531	5,448	5,589	6,407	6,690	TBD
Hitch Weight	526	600	539	736	625	733	816	TBD
Net Carrying Capacity (NCC)	3,000	2,388	3,008	5,448	2,036	4,486	4,286	TBD
Tire Size and Load Range	14″C	14″ C	14″C	15" D	14″C	15″ D	15″ D	TBD
Measurements								
Overall Length	27′ 5″	29′	29′ 2″	29′ 5″	30′3″	33′10″	34′ 8″	TBD
Overall Height (Including A/C)	11′3″	11′3″	10′5″	11′3″	11′3″	11′3″	11′3″	TBD
Exterior Width	96″	96″	96″	96″	96″	96″	96″	96″
Awning Length	14′	19′	14′	14′	21′	18′	17′	TBD
Tank Capacities								
Grey Tank	30	40	30	40	40	35	40	TBD
Black Tank	30	40	30	40	40	35	40	TBD
Fresh Tank (2 - 65 gallon)	30	40	30	40	40	40	40	TBD
T 1 COUR LILL COUR LILL 1 String of the stri								

Towing capacity is limited by GCWR; your vehicle's towing capacity is the difference between the GCWR and the actual vehicle weight, including all water, fuel, passengers and cargo. Your towed vehicle should be equipped with auxiliary brakes if the weight of the towed vehicle exceeds 1,000 lbs. Consult your owner's manual for further towing information.

EXTERIOR: FEATURES

- 8" I-Beam Frame (N/A 26RKS, 27BH)
- .024 Aluminum Skin
- 16" on Center 2 x 2 Stud
- R-7 Insulation
- 5/8" Flooring
- Radius Clamp Ring Windows
- Diamond Plate Front Lower Panel
- · Rubber Roof
- 5"Truss Rafters with 3/8" Decking
- Ducted A/C
- · Enclosed Underbelly
- · Radial Entry Door
- 30# Propane Tanks

INTERIOR: FEATURES

- 82" Interior Height (Super Slide
- 72" Interior Height Slide Room (Super Slide Models)
- Overhead Cabinet in Slide
- Large Galley Countertops

- 60" x 80" Queen Bed
- Entertainment Centers Designed for LCD TV's
- · Rich Golden Select Mortise and Tenon Hardwood Cabinet Doors
- · Toe Kicks on Galley
- Large Stainless Steel Sink
- Picture Window at Dinette
- Large Shower with Skylight
- Power Vent in Bathroom
- Residential Wood Medicine Cabinet with Vanity Light Bar
- · Access Doors at Dinette Ends
- Drawers with Roller Guides
- 5" Arched Dinette Cushions
- · Residential Style Sofa
- Tub Surround
- Full Wardrobes with Drawers in Bedroom
- Two Interior Decors-Windsor Blue and Vintage Moss
- Water Heater Bypass
- Doubled Door Refrigerator

OPTIONS

- Awning
- A/C 13.5 BTU Ducted
- High Capacity Ducted A/C
- Gas/Electric DSI Water Heater
- Carrier A/C with Remote Control
- Roof Ladder
- RVQ Grill
- · Safety Glass
- Spare Tire/Carrier/Cover
- Stabilizer Jacks
- TV Antenna

- 19" LCD TV
- 12 Volt AM/FM CD/DVD Player
- Bedroom Carpet and Pad
- Living Area Carpet and Pad
- Chair (28RLS Only)
- Free Standing Dinette (4 Chairs)
- Hide-A-Bed (Super Slides Only)
- Microwave
- **Outside Shower**
- Oven with 3 Burner Range
- Sink Covers (2)
- · Stove Cover

DECOR OPTIONS



Vintage Moss



Windsor Blue

A. Sofa B. Accent C. Bedroom

D. Carpet







All tank capacities are estimated based upon calculations provided by the tank manufacturers and represent approximate capacities. The actual "usable capacity" may be greater or less than the estimated capacities based upon fabrication and installation of the tanks.

^{***} Actual filled LP capacity is 80% of listing due to safety shut-off required on tank

26 R K S



27BH



28RLS



31BHDS



26BHS



27RBS



3 0 Q B H S




3 2 R L S











Pass Through Storage



Outside Shower





BEING DIFFERENT MAKES ALL THE DIFFERENCE.

Take a closer look, and you'll discover that Holiday Rambler, a brand of Monaco Coach Corporation, gives you more industry "bests" than any other RV manufacturer. The convenience of our 350 service centers. The value of Monaco Financial Services. And the online support of holidayrambler.com. At Holiday Rambler, we've built our reputation by listening to you — and answering to you. And that's the difference that's made us the best.

WARRANTIES

12 Month basic limited warranty

2 Year limited warranty on steel frame structure

PRESIDENTIAL SUITE

PRESIDENTIAL

ALUMASCAPE SUITE

ALUMASCAPE

NEXT LEVEL

SAVOY LE/LX

MINTARO

BLACK DIAMOND

The actual overall length of the recreational vehicle may differ from that indicated in the brochure due to variances in the manufacturing process and/or installed components. The actual length may be greater or less than that indicated. Due to the large variety of options and floorplan arrangements available to our customers, actual weights for each unit can differ significantly. Holiday Rambler provides a weight sticker on each unit we produce which includes that unit's tank capacities and approximate weight. Consult your local Holiday Rambler dealer for unit availability and further information. The information printed in this brochure reflects product design, fabrication, and component parts at the date of printing. In amunifacturer reserves the right, at any time, to make changes in product design or material or component specifications as its sole option, without notice. This includes the substitution of components of a different brand or trade name which will result in comparable performance. All information printed in this brochure is subject to change after the date of printing. Some features shown or mentioned in this brochure are optional and may only be available in selected floorplans. Photographs may show props or decorations that are not standard equipment on Holiday Rambler models. Holiday Rambler logo and its design, are registered trademarks. All other products and company names are trademarks and/or registered trademarks of their respective holders. While the color of the motorhome's exterior and the interior fabrics depicted in this sales brochure are fair and reasonable depictions, the colors depicted may not be an exact match of the actual colors because of the variances in photo-processing and variances caused by inserting the photographs within the sales brochure. Due to product improvements, changes during the model year and/or transcription errors that may occur, information is usually to the variances in photo-processing and variances caused by inserting the photographs within the sal